



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBRABN94A961110	Model Year 2004	License # 5192	Rated Capacity ***** 16
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBRABN24A961109	Model Year 2004	License # 5191	Rated Capacity ***** 16
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number xxxxxxxxxxxx1384	Model Year 2002	License # 1700	Rated Capacity ***** 68
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAANX5A979868	Model Year 2005	License # 1071	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number x1FDWE45X3HB39599	Model Year 2003	License # 1069	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN05A979913	Model Year 2005	License # 1643	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number xxxxxxxxxxxx9890	Model Year 2005	License # 1585	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number xxxxxxxxxxxx6305	Model Year 2001	License # 1550	Rated Capacity ***** 14
Chassis Make Chevrolet	Body Make Other	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN75A979889	Model Year 2005	License # 1618	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN85A979870	Model Year 2005	License # 1615	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN35A979890	Model Year 2005	License # 1585	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN15A979905	Model Year 2005	License # 1586	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAANX5A979904	Model Year 2005	License # 1602	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN45A979879	Model Year 2005	License # 1608	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN75A979911	Model Year 2005	License # 1642	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN55A979907	Model Year 2005	License # 1638	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN15A979869	Model Year 2005	License # 1600	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN95A979912	Model Year 2005	License # 1644	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN75A979908	Model Year 2005	License # 1639	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN55A979910	Model Year 2005	License # 1641	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN35A979906	Model Year 2005	License # 1635	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN45A979915	Model Year 2005	License # 1637	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN95A979909	Model Year 2005	License # 1640	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F43HB39615	Model Year 2003	License # 1598	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45FX3HB39618	Model Year 2003	License # 1597	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN55A979888	Model Year 2005	License # 1632	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F23HB39614	Model Year 2003	License # 1587	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F53HB39588	Model Year 2003	License # 1589	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F43HB39520	Model Year 2003	License # 1599	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F33HB39668	Model Year 2003	License # 1595	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F03HB39630	Model Year 2003	License # 1596	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45FX3HB39621	Model Year 2003	License # 1645	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F53HB39638	Model Year 2003	License # 1592	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F43HB39646	Model Year 2003	License # 1593	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F53HB39641	Model Year 2003	License # 1594	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F43HB39582	Model Year 2003	License # 1588	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F73HB39589	Model Year 2003	License # 1591	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45FX3HB39652	Model Year 2003	License # 1590	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN85A979903	Model Year 2005	License # 1629	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRRSABN0TA072312	Model Year 1996	License # 3010	Rated Capacity ***** 65
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDWE45F83HB39651	Model Year 2003	License # 1070	Rated Capacity ***** 18
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN25A979914	Model Year 2005	License # 1636	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN45A979901	Model Year 2005	License # 1633	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN25A979895	Model Year 2005	License # 1623	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN65A979897	Model Year 2005	License # 1625	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN25A979878	Model Year 2005	License # 1607	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN05A979894	Model Year 2005	License # 1622	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN75A979875	Model Year 2005	License # 1611	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN85A979898	Model Year 2005	License # 1626	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN95A979893	Model Year 2005	License # 1621	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN35A979887	Model Year 2005	License # 1617	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN65A979883	Model Year 2005	License # 1604	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN05A979877	Model Year 2005	License # 1609	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN95A979876	Model Year 2005	License # 1610	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAANX5A979885	Model Year 2005	License # 1603	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN15A979886	Model Year 2005	License # 1616	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN25A979881	Model Year 2005	License # 1605	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN35A979873	Model Year 2005	License # 1613	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN85A979884	Model Year 2005	License # 1601	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAANX5A979871	Model Year 2005	License # 1614	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN05A979880	Model Year 2005	License # 1606	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN55A979874	Model Year 2005	License # 1612	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN45A979896	Model Year 2005	License # 1624	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAANX5A979899	Model Year 2005	License # 1627	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN15A979872	Model Year 2005	License # 1630	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN75A979892	Model Year 2005	License # 1620	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN55A979891	Model Year 2005	License # 1619	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN45A979882	Model Year 2005	License # 1631	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNBXA75F219413	Model Year 2005	License # 1600	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make American	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN65A979902	Model Year 2005	License # 1634	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBWAAN25A979900	Model Year 2005	License # 1628	Rated Capacity ***** 84
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Laidlaw		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAANCSA7TF066490	Model Year 1996	License # 1300	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BAAKCSHXP053289	Model Year 1993	License # 1770	Rated Capacity ***** 72
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION
TO BE FILLED OUT BY THE HIGHWAY PATROL
This inspection is for: ☐ 1st semester ☒ 2nd semester

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.
Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1BABNBXA55F219412	Model Year 2005	License # 1500	Rated Capacity ***** 46
Chassis Make Bluebird	Body Make American	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBHG31RXX1090506	Model Year 1999	License # 1750	Rated Capacity ***** 15
Chassis Make Chevrolet	Body Make Other	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBJG31R511126305	Model Year 2001	License # 1550	Rated Capacity ***** 14
Chassis Make Chevrolet	Body Make Other	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Helena Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1HVBGAAN82A941384	Model Year 2002	License # 1700	Rated Capacity ***** 68
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name East Helena Elementary	
Vehicle I.D. # (VIN) - Entire Number 1HVBBNMP6NH389429	Model Year 1992	License # 1053	Rated Capacity ***** 78
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name East Helena Elementary	
Vehicle I.D. # (VIN) - Entire Number X1BAHBCSHWF078226	Model Year 1998	License # 1744	Rated Capacity ***** 30
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name East Helena Elementary	
Vehicle I.D. # (VIN) - Entire Number 1BABNBXA65F219192	Model Year 2005	License # 1784	Rated Capacity ***** 88
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name East Helena Elementary	
Vehicle I.D. # (VIN) - Entire Number 1BAANCSH9RF054850	Model Year 1994	License # 1553	Rated Capacity ***** 84
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input checked="" type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name East Helena Elementary	
Vehicle I.D. # (VIN) - Entire Number 1T88T3B2711105574	Model Year 2001	License # 1530	Rated Capacity ***** 88
Chassis Make Other	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name East Helena Elementary	
Vehicle I.D. # (VIN) - Entire Number 1BAAHCSH8NF046997	Model Year 1992	License # 1554	Rated Capacity ***** 66
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name East Helena Elementary	
Vehicle I.D. # (VIN) - Entire Number 1BAAGCSH9JF080962	Model Year 1988	License # 1555	Rated Capacity ***** 66
Chassis Make Bluebird	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name East Helena Elementary	
Vehicle I.D. # (VIN) - Entire Number 1T88U4B2XW1163172	Model Year 1998	License # 1375	Rated Capacity ***** 88
Chassis Make Other	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name East Helena Elementary	
Vehicle I.D. # (VIN) - Entire Number 1HVBNEP0MH334231	Model Year 1990	License # 1018	Rated Capacity ***** 72
Chassis Make International	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input checked="" type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Lincoln K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX0057	Model Year 1981	License # 583C	Rated Capacity ***** 60
Chassis Make Chevrolet	Body Make Wayne	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Louri Richards		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Lincoln K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX4569	Model Year 1981	License # 457A	Rated Capacity ***** 65
Chassis Make Chevrolet	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Louri Richards		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Lincoln K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number XXXXXXXXXXXX1011	Model Year 1992	License # 1359	Rated Capacity ***** 44
Chassis Make Bluebird	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input checked="" type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Doug Richards		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Augusta Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBKP32J9P3303125	Model Year 1993	License # 1742	Rated Capacity ***** 29
Chassis Make Chevrolet	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Augusta Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1HVBABP3TH374072	Model Year 1997	License # 1672	Rated Capacity ***** 47
Chassis Make International	Body Make American	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Augusta Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBJ6P1P9LV111133	Model Year 1990	License # 5723	Rated Capacity ***** 42
Chassis Make Chevrolet	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Augusta Public Schools	
Vehicle I.D. # (VIN) - Entire Number 2480	Model Year 1985	License # 2843	Rated Capacity ***** 23
Chassis Make GMC	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input type="checkbox"/> District Owned <input checked="" type="checkbox"/> Contractor Owned If contractor owned, contractor's name is: Amy Mills		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 25 Lewis & Clark		District Name Augusta Public Schools	
Vehicle I.D. # (VIN) - Entire Number 1T88N3B11T1136257	Model Year 1996	License # 1328	Rated Capacity ***** 66
Chassis Make Ford	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☐ 1st semester ☒ 2nd semester
Approved

Approved					Approved				
Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **
C17	Identification - front				C34	Belt cutter **** attached			
C18	Head lamps				C18	Interior lamps			
C10	Color				C18	Ceiling - interior			
C18	Turn signal lamps - front				C21	Seating			
C18	Turn signal lamps - side (post 1987)				C14	Floor			
C18	Red amber signals - front				C9	Aisle			
C18	Marker lamps - front				C22	Tools - storage			
C18	Windshield				C24	Windows			
C24	Windshield wipers				C13	Warning device			
C20	Exterior mirrors				C13	Buzzer emergency door			
C3	Battery				C12	Emergency door			
C4	Generator or alternator				C18	Red amber signals - rear			
C11	Service door				C18	Turn signal lamps - rear			
C6	Head lamp indicator				C18	Stop lamps			
C6	Horn				C18	Marker lamps - rear			
C20	Interior mirror				C19	Strobe light - rear ***			
C6	Speedometer				C17	Identification - rear			
C2	Brakes				C4	Exhaust system (no leaks)			
C21	Driver seat belt				C5	Fuel tank			
C7	Steering gear				C7	Tires (2/32" rear - 4/32" front min.)			
C13	Fire extinguisher (5 lbs)					Cleanliness			
C13	First aid kit				C22	Stop arm			
C13	Body fluids kit				C5	No trailer hitch			
C11	Defroster					Required by forest regulation:			
C6	Heaters					Shovel (securely fastened)			
C20	Wheelchair forward facing (post 1993)					Axe (securely fastened)			

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date